

Professional Audio Products Technical Bulletin 90–045

Sony Corporation of America Technical Publications 677 River Oaks Pkwy, San Jose, California 95134

Analog

Date: May, 1990

Model: APR-24/5000

Serial No: 10,001 AND HIGHER

Subject: POWERING UP WITHOUT PROMS—LOSS

OF PRESET DATA

DESCRIPTION

Powering up an APR-24 or APR-5000 unit without PROMs in IC13 and IC14 on the CPU Board will result in loss of all preset data contained in the battery backed up RAM.

Do not leave IC13 or IC14 vacant at any time.